

LEGEND:

☐ Traffic Crossing Pole
☐ FDOT Hand Hole
☑ Verizon Vault

Hand Hole ⊗ Bollard n Vault ---- Guard Rail Pole **ø** Wood Powe

✓ Mor Marker

✓ Gas Valve

(D) Denotes information taken from Deed

Underground Gas Marker

Underground Gas Marker

d Metal Sign & Post

→ Gas Riser

Concrete Power Pole

Guy Wire

| Concrete Power Pole | Item Number shown in Title Commitment Schedule B-II

C Cable Vault

DESCRIPTION:

That part of the Northwest 1/4 of the Northeast 1/4 of the Southwest 1/4 lying South of U.S. Highway No. 41 and East of West River Road, and also that part of the Southwest 1/4 of the Southeast 1/4 of the Northwest 1/4 lying South of U.S. Highway 41, Section 34, Township 39 South, Range 20 East, Sarasota County, Florida, Less any reservations, conveyances or grants for Right-of-Way purposes for State Road 777 or U.S. Highway No. 41;

AND

That portion of land lying in Sarasota County, Florida, South and East of the centerline of a creek, on the following described property:

A part of the Northeast 1/4 of the Northwest 1/4 of the Southwest 1/4 of Section 34, Township 39 South, Range 20 East, described as follows:

Starting at the centerline of the Intersection of two roads designated as being U.S. 41 a/k/a/ State Route 45, and State Route 777, respectively, and proceeding Easterly along centerline of U.S. 41, 318.2 feet, thence South 54.06 feet to the edge of Right-of-Way of said road to the Point of Beginning; thence Southerly 313.7 feet more or less to the right-of-way of State Road 777; thence Northwesterly along the right-of-way of State Road 777, 314.85 feet more or less to intersect the right-of-way of road U.S. 41; thence Easterly along the right-of-way;

AND ALSO LESS that real property described as:

That portion of the Northwest 1/4 of the Northeast 1/4 of Section 34, Township 39 South, Range 20 East, Sarasota County, Florida, more particularly described as follows:

Begin at the intersection of the East existing right-of-way line of County Road 777, (River Road) (per Project 17060-2502) and the South existing right-of-way line of Ù.S. 41 (State road 45/Tamiami Trail) (per project 17010-2508) and the beginning of a curve concave Northerly; thence along said South existing right-of-way line on the arc of said curve having a radius of 3031.73 feet, a central angle of 01°34'27", an arc length of 83.29 feet, the chord for which bears N.75°41'59"E. to the end of said curve; thence S.46°02'32"W., 51.43 feet; thence S.36°40'52"E., 92.00 feet; thence S.42°00'48"E. 150.65 feet; thence S.36°40'52"E. 148.51 feet; to the beginning of a curve concave Southwesterly; thence along the arc of said curve having a radius of 5829.58 feet, a central angle of 01°04'50" an arc length of 109.95 feet, the chord for which bears S.36°08'26"E. of the South line of the Northwest 1/4 of the Northeast 1/4 of the Southwest 1/4 of said Section 34 and the end of said curve; thence along said line N.89°25'37"W., 47.56 feet to the east maintained right-of-way line of said County Road 777; thence along said maintained right-of-way line the following three courses, N.35°44'19"W., 27.70 feet; N.32°22'22"W., 178.74 feet; N.42°09'34"W., 157.11 feet to the end of said courses and to the East existing right-of-way line of said County Road 777, thence along said existing right-of-way line N.36°40'52"W., 147.48 feet to the Point of Beginning, as per Florida Department of Transportation right-of-way map for County Road 777 (River Road).

REPORT OF SURVEY:

- This plat represents a Boundary Survey showing visible improvements.
- 2. Bearings shown hereon refer to an assumed meridian, The East ine of Section 34 as having a bearing of S.00°47'13"E.
- 3. There may exist other underground fixed interior
- improvements, which are not visible and are not a part of this survey.
- 4. Description shown hereon has been taken from Title Report
- provided by Flash Investors, LLC, Fund File Number: 1303050 A1.

 5. Subject to easements and rights of way of record, if any. No research has been made of easements or rights
- of ways of record. No easements shown on Record Plat.
 6. Attorneys' Title Fund Services, LLC, Title Search Report Fund File
- 6. Attorneys' Title Fund Services, LLC, Title Search Report Fund File Number 1303050 A1, Dated February 9, 2023 and Title Search Report Fund File Number 1303050, dated January 27, 2023.

Standard Exceptions:

Items 1, 2, 4, 7, and 8 are not a matter of land surveying.

Item 3 is applicable, and blanket in nature, not depicted hereon.

Items 5 and 6 are not applicable.

Restrictions/Easements:

Item 1 is applicable, blanket in nature, not depicted hereon.

Items 2 and 3 are applicable and depicted hereon.

Items 4 and 5 are not applicable.

Items 6 and 7 are not matters of land surveying.

7. Parcel shown hereon is situated in Flood Zone "AE",
base flood elevation = 7 feet, and Flood Zone "X500", base
flood elevation Not Determined, per current Flood Insurance Rate

Map 12115C0370F, Index Map dated November 4, 2016.

8. Accuracy: The expected use of the land is "Suburban".

The minimum relative distance accuracy for this type of boundary survey is 1 foot in 7,500 feet. The accuracy obtained by measurement and calculation of a closed geometric figure was found to exceed this requirement.

9. (P) Denotes information obtained from record Plat.

(P) Denotes information obtained from Field measurement.

CURVE TABLE

CURVE	RADIUS	ARC LENGTH	CHORD LENGTH	CHORD BEARING	DELTA ANGLE
C1	5159.28	101.26'	101.26'	S 35°59'07" E	01°07'28"
C2	3031.73	176.02'	175.99'	S 73°14'33" W	03°19'35"
C3	3016.73	312.06'	311.92'	S 68°37'39" W	05°55'36"
C4	3031.73	156.79'	156.77	S 64°07'38" W	02°57'47"
C5	3021.73	44.45	44.45'	S 62°22'34" W	00°05'34"

