


November 4, 2016

North Port WWTP
North Port, FL
Condition Report #2 Clarifier
Attn.: Mark Sutton

Mark:

During our leveling work on Clarifier #2 (November 2015), it was discovered that the existing influent/support column has been structurally compromised from corrosion around the liquid level area. This condition has resulted in the out of levelness of the clarifier mechanism. Our contractor brought the machine back to level. As the column continues to corrode, the machine will go out of level again. We recommend the City considers replacing the column.



Elevation view of the existing
Influent/support column.

Our exclusive agent for this equipment in your geographic area is:

TSC Jacobs

11021 Countryway Blvd.
Tampa, FL 33626

Austin Moore
813 888-5556 - Office
813 300-7415 – Mobile
austin@tscjacobs.com

Please direct all inquiries for municipal wastewater treatment equipment to above agent.

Respectfully,



Bill Stewart
Sales Engineer
Ovivo USA, LLC Rebuild Group
801 931-3265
bill.stewart@ovivowater.com