


# OPTION A - STAIRWELL



**Estimated Installation Cost: \$250**

**Considerations:** Low cost, no need to alter sculpture, easy to install location, able to see sculpture from several different angles, cost of installation could be covered by existing facilities budget.

# OPTION B - SECOND FLOOR LOBBY



**Estimated Installation Cost: \$2,140**

**Considerations:** Easy electrical access for downlighting but the need for concrete scanning increases price. Would need to remove and cap light fixture. Multiple access points to lobby, so there isn't an easily identified way that the Spoonbill should 'face'.

# OPTION C - SECOND FLOOR LOBBY 'ARCHED OUT SECTION'



**Facing the Main Building Entrance**

# OPTION C - SECOND FLOOR LOBBY 'ARCHED OUT SECTION', CONT.



**Facing Chambers**

**Estimated Installation Cost: \$1,080**

**Considerations:** No concerns with the fire door clearance. Not easily visible from main lobby on first floor. Would require alteration to the 'height'. There are multiple access points to lobby, so there isn't an easily identified way that the Spoonbill should 'face'.