

**Asset Disposition and Recommended Method of Disposal  
December 2022**

	<b>CID #</b>	<b>YEAR</b>	<b>Description</b>	<b>DEPT</b>	<b>Mileage/Hrs</b>	<b>Condition</b>	<b>Reason for Disposal</b>	<b>Method of Disposal</b>	<b>Estimate Value</b>	<b>NOTES</b>
1	72468	2015	Chevy Tahoe	PD	91,645	Poor	Replaced	Auction	\$5,000.00	Blown Motor
2	72473	2015	Chevy Tahoe	PD	109,317	Poor	Replaced	Auction	\$5,000.00	Blown Motor
3	72475	2015	Chevy Tahoe	PD	101,144	Poor	Replaced	Auction	\$5,000.00	Blown Motor
4	72531	2015	Chevy Tahoe	PD	101,144	Poor	Replaced	Auction	\$5,000.00	Blown Motor
5	72540	2015	Chevy Tahoe	PD	109,317	Poor	Replaced	Auction	\$5,000.00	Blown Motor
6	70571	2005	Sterling Dump	R&D	79,205	Poor	Replaced	Auction	\$50,000.00	Parts to repair no longer available
7	71484	2009	Cat 308	R&D	1,062	Poor	Replaced	Auction	\$10,000.00	Parts to repair not available
8	71561	2011	Ford F350	R&D	70,853	Poor	Replaced	Auction	\$10,000.00	Repairs in excess of \$4500
9	71671	2012	Ford F550	R&D	76,766	Poor	Replaced	Auction	\$20,000.00	Motor issues
10	71618	2011	Crane Carrier - Rear Load	SW	137,208	Poor	Replaced	Auction	\$50,000.00	
11	72410	2014	AutoCar - Side Load	SW	83,710	Poor	Replaced	Auction	\$50,000.00	
12	72449	2014	AutoCar - Front Load	SW	77,847	Poor	Replaced	Auction	\$50,000.00	
13	72452	2014	AutoCar - Side Load	SW	82,979	Poor	Replaced	Auction	\$50,000.00	
14	73028	2017	Curotto Can	SW	0	Poor	Replaced	Auction	\$1,000.00	No Longer repairable
15	73039	2017	Curotto Can	SW	0	Poor	Replaced	Auction	\$1,000.00	No Longer repairable
16	73140	2017	Curotto Can	SW	0	Poor	Replaced	Auction	\$1,000.00	No Longer repairable
17	73141	2017	Curotto Can	SW	0	Poor	Replaced	Auction	\$1,000.00	No Longer repairable
18	73251	2018	Curotto Can	SW	0	Poor	Replaced	Auction	\$1,000.00	No Longer repairable
19	70133	2003	Ford F550	Fire	127,455	Poor	Replaced	Auction	\$20,000.00	Extensive motor issues
20	71222	2008	Ford F250	P&G	119,088	Poor	Replaced	Auction	\$10,000.00	Blown Motor, repair exceeds value
21	70554	2005	Cat304	Utilities	2,313	Poor	Replaced	Auction	\$5,000.00	Extensive repairs needed