

RFB 2025-43 Inflow and Infiltration (Florida Department of Economic Opportunity's Rebuild Florida Infrastructure Repair Program)

Schedule	Description	Quantity (2)	Unit	Vortex Services, LLC		GCU, LLC		Inliner Solutions, LLC	
				Unit Cost	Item Cost	Unit Cost	Item Cost	Unit Cost	Item Cost
REHABILITATION (1)									
	CURED-IN-PLACE LINER								
1	Cured in Place Liner - 8" Dia. (6 mm thick)	3937	LF	\$60.00	236,220.00	99.50	391,731.50	\$44.00	173,228.00
2	Cured in Place Liner - 10" Dia. (6 mm thick)	3249	LF	\$61.00	198,189.00	117.50	381,757.50	\$46.00	149,454.00
3	Reinstate Service Lateral Connection	101	EA	\$120.00	12,120.00	538.50	54,388.50	\$50.00	5,050.00
4	Sealing Service Lateral Connection via Chemical Grouting	101	EA	\$425.00	42,925.00	1,923.50	194,273.50	\$400.00	40,400.00
				GRAND TOTAL:	489,454.00		1,022,151.00		368,132.00

Note 1 Rehabilitation unit costs include all work to construct, test and inspect (including but not limited to maintenance of traffic, taking samples and having them tested at a lab, cleaning/preparing pipe and manholes, pre and post rehabilitation CCTV, and bypass pumping).

Note 2 Quantities shown are estimated to establish unit pricing for each specific item and give a general scope of the project. Final project quantities may be increased or decreased based on actual quantities and/or budget dollars available.

Date:

Authorized to Bind Company

Name (printed)