

Additional Comments:



Inventory CID: 72468	Vin #: 1GNLC2EC3FR515556	Fair Market Value: \$ 4,0000	
Short Description:		•	
Year: <u>2015</u> Make: <u>Chevrolet</u>	Model: <u>Tahoe</u>	Mileage: 9/773	
This Vehicle: Starts Start	s with a boost and 💢 Runs 🔲 Doe	s not Run For Parts Only	
Engine: <u>5.3</u> L V <u>Q</u>	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>3000</u> Days Hours	Miles	
	epair 🔲 Is in unknown condition		
Repairs Needed (Be specific):	Motor NOISE BOWN	ergine	
	*	_Est Cost of Repairs: \$	
Date removed from service:	/ / Maintenance F	Records: Avail Not Avail	
Transmission:			
🗹 Automatic 🔲 Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:	NORE		
	Major Damage to		
□AC □No AC AC Condition: □Cold □Unknown Air Bags: □Driver's Side □Dual			
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
Exterior: Color black Windows: No cracked glass Cracked:			
	Dings Tire Condition: Good 🗌 Low 🚶		
	Major Dents to:		
	s been removed \Box there are holes in th		
	on: MFG Model		
	o ZONAR Removed: ☐Yes ☐No ☐N/A	N. Comments of the Comments of	
Lights/ACC removed: Yes			
	No Keys/KeyTrak ☐Yes ☐ No		
	Date: 8/2//2	\leq	
	Date: <u>\delta / \delta /</u>		
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_ YES NO N/A	





Inventory CID: 72473	Vin #: 1GNLC2EC2FR513975	Fair Market Value: \$ 4,000 000	
Short Description:			
Year: 2015 Make: Chevrolet	Model: <u>Tahoe</u>	Mileage: 94893	
This Vehicle: Starts Start	s with a boost and Runs Does	s not Run For Parts Only	
Engine: <u>5.3</u> L V <u>§</u>	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>3000</u> Days Hours	Miles	
Condition: Runs Needs R	epair sin unknown condition		
Repairs Needed (Be specific):	motor skip. Blo	own engine	
	· · · · · · · · · · · · · · · · · · ·	_Est Cost of Repairs: \$	
Date removed from service:	// Maintenance F	Records: Avail Not Avail	
Transmission:			
	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
	Major Damage to		
□AC ☒No AC AC Condition: □Cold ☒Unknown Air Bags: ☒Driver's Side □Dual			
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
	ndows: X No cracked glass Cracke		
Minor Dents ✓ Scratches ✓ Dings Tire Condition: Good ✓ Low ☐ lat ☐ Hubcaps 1 2 3 4			
	Major Dents to:		
Emergency Equip: None Has been removed there are holes in the exterior			
Additional Equipment Description: MFG Model Serial #			
Lic Plates removed: Yes No ZONAR Removed: Yes No N/A			
Lights/ACC removed:Yes No N/A			
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No			
Mechanic's name: Daminick Date: 8/27/22			
Approved by: Date: $8/97/99$			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			
Additional Comments:			





Inventory CID: 72475	Vin #: 1GNLC2EC3FR51771	.3 Fair Market	Value: \$ 4,000,00
Short Description:			-
Year: 2015 Make: Chevrolet			
This Vehicle: Starts Starts Engine: 5.3 L V S	ts with a boost and 💢 Run	s Does not Run	For Parts Only
Engine: <u>5.3</u> L V <u>§</u>	Gas Diesel Engine		
This Vehicle was maintained eve	ery 3000 Days	☐Hours Miles	
Condition: Runs Needs Ro	epair 🔲 ls in unknown con	dition	12 \ 11
Repairs Needed (Be specific):	motor skip	/ check Eng.	right on Da To
	/	Est Cost of	Repairs: \$
Date removed from service:	/ / Ma	intenance Records:	Avail Not Avail
Transmission:			
💢 Automatic 🔲 Manual	Condition is: Operable	Needs Repair 🔲 Is	Unknown
Transmission repairs needed:	NONC		
Minor Damage to:			
□AC □No AC AC Condition:			
Cruise Tilt Wheel Remot			
Exterior: Color 50001 Wir			
Minor Dents Scratches C			
Minor Dents to:			
Emergency Equip ☐ None ☐ Ha			
Additional Equipment Description			rial #
Lic Plates removed: ☐Yes ☐No		_No L_N/A	
Lights/ACC removed: Yes		í. m.	
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No			
Mechanic's name: Dominick Date: 8/27/22			
Approved by: Date: Date: YES NO N/A			
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORA	AGE: YES	NON/A
Additional Comments:			





Inventory CID: 72531	Vin #: 1GNLC2EC1FR577571	Fair Market Value: \$ 9,000	
Short Description:		•	
Year: <u>2015</u> Make: <u>Chevrolet</u>	Model: <u>Tahoe</u> s with a boost and	Mileage: 48,389	
This Vehicle: Starts Start	s with a boost and 🏻 Runs 🔝 Doe	s not Run For Parts Only	
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>3,000</u> DaysHours	Miles	
Condition: Runs Needs Re	epair Is in unknown condition		
Repairs Needed (Be specific):	Bag engin		
		Est Cost of Repairs: \$	
Date removed from service:	// Maintenance	Records: Avail Not Avail	
Transmission:			
Automatic	Condition is: ✓ Operable ☐ Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to:	Major Damage to	:	
XAC No AC AC Condition: No AC	Cold□UnknownAir Bags:□Dri	ver's Side 🔀 Dual	
☑Cruise ☑Tilt Wheel ☑Remote Mirrors □Climate Ctr - PWR:☑ Windows ☑Locks ☑Steering ☑Seats			
Exterior: Color Wik/white Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low Ital Hubcaps 1 2 3 4			
	Major Dents to:		
Emergency Equip None Has been removed there are holes in the exterior there are no holes			
Additional Equipment Description: MFG Model Serial #			
Lic Plates removed: Yes No ZONAR Removed: Yes No VN/A			
Lights/ACC removed: Yes No N/A			
Fuel Card Turned in: Yes □ No Keys/KeyTrak □Yes □ No			
Mechanic's name: Date: $8/27/22$ Approved by: Date: $8/27/22$			
Approved by: Date: Date: Date:			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			





Inventory CID: 72540	Vin #: 1GNLC2EC5FR577170	Fair Market Value: \$ 4 av ***	
Short Description:			
Year: 2015 Make: Chevrolet	Model: <u>Tahoe</u>	Mileage:	
This Vehicle: Starts Start	s with a boost and 🙀 Runs 🔲 Doe	s not Run For Parts Only	
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery 3,000 Days Hours		
Condition: Runs Needs Re	epair 🔲 ls in unknown condition		
Repairs Needed (Be specific):	Bad er	give	
		_Est Cost of Repairs: \$	
Date removed from service:	// Maintenance F	Records: Avail Not Avail	
Transmission:			
Automatic Manual	Condition is: \square Operable \square Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to:	Major Damage to	:	
AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual			
Cruise ☑Tilt Wheel ☑Remote Mirrors □Climate Ctr - PWR:☑ Windows ☑Locks ☑Steering ☑Seats			
Exterior: Color Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low I lat Uhubcaps 1 2 3 4			
	Major Dents to:		
Emergency Equip: None Has been removed there are holes in the exterior there are no holes			
Additional Equipment Description: MFG Model Serial #			
Lic Plates removed: Yes No ZONAR Removed: Yes No XN/A			
Lights/ACC removed: Yes No N/A			
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No			
Mechanic's name: Date: $8/37/32$			
Approved by: Date: $\frac{3}{2}/\frac{37}{29}$			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			





Inventory CID: 70571	Vin #: 2FZACGDC05AV38883	Fair Market Value: \$ 8,500 00
Short Description:		,
Year: 2005 Make: Sterling	Model: <u>Dump Truck</u>	Mileage: <u>79093</u>
This Vehicle: Starts Start	s with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only
Engine:L V_6	Gas Diesel Engine C7-Cat	
This Vehicle was maintained eve	ery 7500 Days Hours	Miles
Condition: Runs Needs Re	epair ls in unknown condition	, ,
Repairs Needed (Be specific):	check Engine lig.	ht on Muns rough
		-
Date removed from service:	// Maintenance F	Records: Avail Not Avail
Transmission:		
Automatic 🔲 Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown
Transmission repairs needed:		
Minor Damage to:	Major Damage to	:
	Cold Unknown Air Bags: Driv	
	e Mirrors Climate Ctr - PWR: Wind	
	dows: 🔀 No cracked glassCracke	4
	Dings Tire Condition: Good 🗌 Low	
	Major Dents to:	
	s been removed \Box there are holes in th	
	on: MFG Model	
Lic Plates removed: Yes	o ZONAR Removed: Kes No N/A	
Lights/ACC removed: Yes		
Fuel Card Turned in: Yes	No Keys/KeyTrak Yes No	3
Mechanic's name:	Date: 8/27/22	<u>Z</u>
Approved by:	Date: <u>\&</u> / <u>\delta \equiv / \delta \eq</u>	· · · · · · · · · · · · · · · · · · ·
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A





Inventory CID: 71484	Vin #: CAT0308DPGBT00276	Fair Market Value: \$ 8,000
Short Description:		
Year: <u>2009</u> Make: <u>Caterpillar</u>	Model: Excavator 308D	Mileage: 4(9)
This Vehicle: Starts Starts	s with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only
Engine:L V		
This Vehicle was maintained eve	ry	Miles
Condition: Runs Needs Re	pair Is in unknown condition	
Repairs Needed (Be specific):		Track frame pusted
		Est Cost of Repairs: \$
Date removed from service:	// Maintenance I	Records: Avail Not Avail
Transmission:		
X Automatic Manual	Condition is: ☐ Operable ☐ Needs Re	pair 🔲 Is Unknown
Transmission repairs needed:		
Minor Damage to:	Major Damage to	Track Frame
☐AC ☐No AC AC Condition:☐]Cold ⊠Unknown Air Bags: □Dri	ver's Side Dual
☐Cruise ☐ Tilt Wheel ☐ Remote	e Mirrors \square Climate Ctr - PWR: \square Wind	lows Locks Steering Seats
	dows: 🔀 No cracked glass Cracke	
Minor Dents Scratches D	rings Tire Condition: Good Low [flat □Hubcaps 1 2 3 4
Minor Dents to:	Major Dents to:	
Emergency Equip None Has	s been removed $\Box_{ m t}$ here are holes in tl	he exterior \Box rhere are no holes
Additional Equipment Description	n: MFG Model	Serial #
Lic Plates removed: Yes No	ZONAR Removed: Yes No N/A	A
Lights/ACC removed: Yes	No N/A	
Fuel Card Turned in: Yes N	No Keys/KeyTrak ☐Yes ☐ No	
Mechanic's name:	Date: $8/27/37$	
Approved by:	Date:	. /
FOR PD VEHICLE: SEAT PUT BAC	CK IN VEHICLE FROM STORAGE:	_YESNON/A
Additional Comments:		/



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT **FLEET MANAGEMENT DIVISION**



MECHANIC'S VEHICLE INSPECTION FORM

Inventory CID: 71561	Vin #: 1FTRF3BT2BEA30864	Fair Market Value: \$ 3,500	
Short Description:		, ,	
Year: 2011 Make: Ford	Model: <u>F550</u>	Mileage: 70883	
	ts with a boost and 💢 Runs 🔲 Doe		
Engine: 2.7 L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>3,000</u> DaysHours	Miles	
	epair sin unknown condition		
Repairs Needed (Be specific):	Oil leals Turbo leaking	Smokins	
*		Est Cost of Repairs: \$	
Date removed from service:	// Maintenance I	Records: Avail Not Avail	
Transmission:			
💢 Automatic 🔲 Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to:	Major Damage to	·	
☑AC ☐No AC AC Condition:	Cold Unknown Air Bags: Dri	ver's Side X Dual	
☑Cruise ☑Tilt Wheel ☑Remote Mirrors □Climate Ctr - PWR:☑ Windows ☑Locks ☑Steering □Seats			
Exterior: Color White Wir	ndows: 🔲 No cracked glass Cracke	ed:	
	Dings Tire Condition: Good \square Low [· -	
	Major Dents to:	the state of the s	
Emergency Equip: None Ha	s been removed $\Box_{\!\! m t}$ here are holes in tl	ne exterior There are no holes	
Additional Equipment Description			
Lic Plates removed: Yes \(\subseteq \text{Ves} \)	o ZONAR Removed:□Yes 风No □N/A	4	
Lights/ACC removed: Yes	No N/A		
	No Keys/KeyTrak Lyes LNo		
	Date: 3/27/37	<u> </u>	
Approved by:	Date: <u>\\</u> / <u>\}\</u> /		
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A	



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT FLEET MANAGEMENT DIVISION



MECHANIC'S VEHICLE INSPECTION FORM

Inventory CID: 71671	Vin #: 1FDUF5HT4CEA44095	Fair Market Value: \$ 3,500 00	
Short Description:			
Year: <u>2012</u> Make: <u>Ford</u>	Model: <u>F550</u>	Mileage: <u>76766</u>	
This Vehicle: Starts Start	s with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only	
Engine: <u>6.7</u> L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery 3,000 Days Hours	Miles	
	epair Is in unknown condition		
Repairs Needed (Be specific): 📐	as check engine light on		
	3 3	Est Cost of Repairs: \$	
Date removed from service:	// Maintenance I	Records: Avail Not Avail	
Transmission:			
💢 Automatic 🔲 Manual	Condition is: ☐ Operable ☐ Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to:	Major Damage to	: <u></u>	
☑AC ☐No AC AC Condition:[]	ŬCold □Unknown Air Bags: □Dri	ver's Side Dual	
☑Cruise ☑Tilt Wheel ☑Remote Mirrors □Climate Ctr - PWR: ☑ Windows ☑Locks ☑Steering □Seats			
	dows: No cracked glass Cracke	The state of the s	
	Dings Tire Condition: Good X Low [
	Major Dents to:		
Emergency Equip None Ha	s been removed \Box there are holes in tl	ne exterior \Box There are no holes	
	on: MFG Model		
Lic Plates removed: Yes No	o ZONAR Removed: ☐Yes ҲNo ☐N/A		
Lights/ACC removed: Yes			
Fuel Card Turned in: Yes	No Keys/KeyTrak Yes No		
Mechanic's name:	Date: 0 / 0 / 0 / 0 / 0 / 0 / 0 / 0 / 0 / 0		
Approved by:	Date: 8 / 37 / 37		
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A	





Inventory CID: 71618	Vin #: 1CYCHL58XBT049938	Fair Market Value: \$	
Short Description:			
Year: 2011 Make: Crane Carrier	Model: <u>Rear Load</u>	Mileage: <u>135286</u>	
This Vehicle: Starts Starts	s with a boost and 💢 Runs 🔲 Does	s not Run For Parts Only	
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>6,000</u> Days Hours	Miles	
Condition: Runs Needs Ro	epair 🔲 ls in unknown condition		
Repairs Needed (Be specific):			
		_Est Cost of Repairs: \$	
Date removed from service:	// Maintenance F	Records: 🗖 Avail 🔲 Not Avail	
Transmission:			
X Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
	DNC Major Damage to		
□AC □No AC AC Condition: □Cold ☑Unknown Air Bags: □Driver's Side □Dual			
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
Exterior: Color white Windows: No cracked glass Cracked:			
Minor Dents Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4 Minor Dents to: Front Bumpel Major Dents to:			
Minor Dents to: Front	Bumper Major Dents to:		
Emergency Equip None Ha	s been removed \Box there are holes in th	ne exterior There are no holes	
Additional Equipment Description		Serial #	
Lic Plates removed: ☐Yes ☐No	o ZONAR Removed: 🔀 es 🔲 No 🔲 N/A		
Lights/ACC removed: Yes	No N/A		
Fuel Card Turned in: XYes	No Keys/KeyTrak Kyes ☐ No		
Mechanic's name: DominiCi	No N/A No Keys/KeyTrak XYes□No L Date: 9/3/22		
Approved by:	/ Date://		
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			





Inventory CID: 72410	Vin #: 5VCACRVF2EH217333	Fair Market Value: \$ 5000 00		
Short Description:		?		
	Model: <u>Side Load</u>	Mileage: 83709 Discrepary?		
This Vehicle: Starts Start	s with a boost and 🔲 Runs 🛮 🗖 Does	s not Run For Parts Only		
Engine:L V	Gas Diesel Engine			
This Vehicle was maintained eve	ery <u>6</u> 600 DaysHours	Miles		
Condition: Runs Needs Re	epair Is in unknown condition			
Repairs Needed (Be specific):	Nostart			
		_Est Cost of Repairs: \$		
Date removed from service:	// Maintenance F	Records: Avail Not Avail		
Transmission:				
	Condition is: Operable Needs Re	oair 🔲 Is Unknown		
Transmission repairs needed:				
Minor Damage to: Body	/(ムb Major Damage to:			
□AC ☑No AC AC Condition: □Cold ☑Unknown Air Bags: □Driver's Side □Dual				
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats				
	Exterior: Color Wh, Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4				
Minor Dents to: Major Dents to:				
Emergency Equip None Has	s been removed \Box there are holes in th	ne exterior There are no holes		
	on: MFG Model			
2) ZONAR Removed: ₩ee No N/A			
Lights/ACC removed: No N/A				
Fuel Card Turned in: Yes I	No Keys/KeyTrak ☐Yes ☐No			
Mechanic's name:	Date: 10 1 19 18	<u> </u>		
Mechanic's name:				
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A		
Additional Comments:				





Inventory CID: 72449	Vin #: 5VCACRVF0EH217329	Fair Mark	ket Value: \$
Short Description:			
Year: 2014 Make: Auto Car	Model: <u>Front Load</u>	Mileage:	7/036
This Vehicle: Starts Starts	s with a boost and 💢 Runs	Does not Run	For Parts Only
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>6,000</u> Days	_Hours ∑Mi	les
Condition: Runs Needs Re	epair Is in unknown cond	tion	
Repairs Needed (Be specific):	Right side Door,	latch miss	ing, Joy Stick missing
AC switch m	issing, Drivers "	Tirror MEST Cost	of Repairs: \$
Date removed from service:	/ Main	tenance Records:	Avail Not Avail
Transmission:			′
X Automatic Manual	Condition is: Operable	Needs Repair 🔃	Is Unknown
Transmission repairs needed:			
Minor Damage to:	Major D	amage to:	NONC.
AC No AC AC Condition:	Cold Unknown Air Ba	ags: Driver's Side	Dual
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
Exterior: Color White. Wir	ndows: 🔀 No cracked glass	Cracked:	
Minor Dents Scratches	Dings Tire Condition: Good	Low Katat L	Hubcaps 1 2 3 4
Minor Dents to: Paint			
Emergency Equip None Ha	s been removed there are	holes in the exterio	r There are no holes
Additional Equipment Description	. ,		Serial #
Lic Plates removed: Yes \(\subseteq \)	o ZONAR Removed:XYes	No N/A	
Lights/ACC removed: Yes			
Fuel Card Turned in: Yes	No Keys/KeyTrak 🕮	es 🗆 No	
Mechanic's name: Dominio			
Approved by: Date://			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			
Additional Comments:			





Inventory CID: 72452	Vin #: 5VCACRVF0EH217332	Fair Market Value: \$
Short Description:	Front load.	
Year: 2014 Make: Auto Car	Model: <u>Side Load</u>	Mileage: <u>83054</u>
This Vehicle:	ts with a boost and 💢 Runs 🛭	Does not Run For Parts Only
Engine:L V		
This Vehicle was maintained ev	ery 7,500 Days H	lours XMiles
Condition: Runs Needs R	epair Is in unknown condition	1
Repairs Needed (Be specific): _		
	·	Est Cost of Repairs: \$
Date removed from service:	// Maintena	ance Records: Xavail Not Avail
Transmission:		4- 4
Automatic Manual	Condition is: Operable Need	ds Repair 💢 Is Unknown
Transmission repairs needed: _		
Minor Damage to:	Major Dama	ge to:
AC No AC AC Condition:	Cold Unknown Air Bags:	Driver's Side Dual
Cruise Tilt Wheel Remo	te Mirrors Climate Ctr - PWR:	Windows Locks Steering Seats
Exterior: Color White Wir	ndows: No cracked glassC	Cracked:
Minor Dents Scratches XI	Dings Tire Condition: Good ☐ L	ow Hat Hubcaps 1 2 3 4
	Major Dents to:	
		s in the exterior There are no holes
Additional Equipment Description	on: MFG Model_	Serial #
Lic Plates removed: Yes LN	o ZONAR Removed: Yes No [N/A
Lights/ACC removed: Yes	No N/A	
Fuel Card Turned in: Yes	No Keys/KeyTrak Xyes C	No
Mechanic's name: Dominio	\mathcal{CK} Date: $9/3/$	22
Approved by:	Date: / /	
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	YES NO N/A





Inventory CID: 73028	Vin #: 11217	Fair Market Value: \$ 35000	
Short Description:			
Year: 2017 Make: Slammin Eagle	Model: <u>Curotto Can</u>	Mileage:	
This Vehicle: Starts Start	s with a boost and Runs Doe	s not Run For Parts Only	
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery Days Hours	Miles	
Condition: Runs Needs Ro	epair 🔲 ls in unknown condition		
Repairs Needed (Be specific):			
		_Est Cost of Repairs: \$	
Date removed from service:	// Maintenance I	Records: Avail Not Avail	
Transmission:			
Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to: Major Damage to:			
AC No AC AC Condition:	□Cold □Unknown Air Bags: □Dri	ver's Side Dual	
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
Exterior: Color Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low Ital Hubcaps 1 2 3 4			
The state of the s	Major Dents to:		
Emergency Equip None Has been removed there are holes in the exterior there are no holes			
Additional Equipment Description	on: MFG Model	Serial #	
Lic Plates removed: Yes No ZONAR Removed: Yes No AV/A			
Lights/ACC removed: Yes No NA			
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No			
Mechanic's name: Date: $10 / 19 / 22$ Approved by: Date: $10 / 19 / 22$			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE:YESNO/_N/A			
		¥	





Inventory CID: 73039	Vin #: 11216	Fair Market Value: \$ \$50,00
Short Description:		
Year: 2017 Make: Slammin Eagle	Model: <u>Curotto Can</u>	Mileage:
This Vehicle: Starts Start	ts with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only
Engine:L V	Gas Diesel Engine	
This Vehicle was maintained eve	ery Days Hours	Miles
Condition: Runs Needs R	epair 🔲 ls in unknown condition	
Repairs Needed (Be specific):		
Date removed from service:	// Maintenance	Records: Avail Not Avail
Transmission:		
Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown
Transmission repairs needed:		
Minor Damage to:	Major Damage to	: Everything
☐AC ☐No AC AC Condition:	☐Cold ☐Unknown Air Bags: ☐Dri	ver's Side Dual
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats		
Exterior: Color Wir	ndows: No cracked glass Cracke	ed:
Minor Dents Scratches Dings Tire Condition: Good Low Ital Hubcaps 1 2 3 4		
	Major Dents to:	
Emergency Equip None Has been removed there are holes in the exterior there are no holes		
Additional Equipment Description: MFG Model Serial #		
Lic Plates removed: Yes No ZONAR Removed: Yes No M/A		
Lights/ACC removed: Yes No N/A		
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No		
Mechanic's name:		
Approved by: Date:\0/_\q_ / \gamma^2		
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE:YESNO/_N/A		





Inventory CID: 73140	Vin #: 11676	Fair Market Value: \$ 250,00
Short Description:		
Year: 2017 Make: Slammin Eagle	Model: <u>Curotto Can</u>	Mileage:
This Vehicle: Starts Start	ts with a boost and 🔲 Runs 🔲 Does	s not Run For Parts Only
Engine:L V	Gas Diesel Engine	
This Vehicle was maintained eve	ery Days Hours	Miles
Condition: Runs Needs Re	epair 🔲 ls in unknown condition	
Repairs Needed (Be specific):		
		_Est Cost of Repairs: \$
Date removed from service:	/ / Maintenance F	Records: Avail Not Avail
Transmission:		
Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown
Transmission repairs needed:		
	Major Damage to:	
☐AC ☐No AC AC Condition:	□Cold □Unknown Air Bags: □Driv	ver's Side Dual
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats		
Exterior: Color Win	dows: No cracked glass Cracke	d:
Minor Dents Scratches Dings Tire Condition: Good Low Ital Hubcaps 1 2 3 4		
Minor Dents to:	Major Dents to:	
Emergency Equip: None Has been removed there are holes in the exterior there are no holes		
Additional Equipment Description: MFG Model Serial #		
Lic Plates removed: Yes No ZONAR Removed: Yes No N/A		
Lights/ACC removed: Yes No N/A		
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No		
Mechanic's name: $96000000000000000000000000000000000000$		
Approved by: Date: <u>\\gamma\g</u>		
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	YES NO N/A





Inventory CID: 73141	Vin #: 11677	Fair Market Value: \$ 250.00
Short Description:		
Year: 2017 Make: Slammin Eagle	Model: <u>Curotto Can</u>	Mileage:
This Vehicle: Starts Start	ts with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only
Engine:L V	Gas Diesel Engine	
This Vehicle was maintained eve	ery Days Hours	Miles
Condition: Runs Needs R	epair Is in unknown condition	
Repairs Needed (Be specific):		
		_Est Cost of Repairs: \$
Date removed from service:	// Maintenance F	Records: Avail Not Avail
Transmission:		
Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown
Transmission repairs needed:		
	Major Damage to	
AC No AC AC Condition:	Cold Unknown Air Bags: Driv	ver's Side Dual
	te Mirrors Climate Ctr - PWR: Wind	
The state of the s	ndows: No cracked glass Cracke	
Minor Dents Scratches I	Dings Tire Condition: Good \square Low [■ Hubcaps 1 2 3 4
	Major Dents to:	
	s been removed \Box there are holes in the	
	on: MFG Model	
Lic Plates removed: Yes No ZONAR Removed: Yes No M/A		
Lights/ACC removed:Yes No N/A		
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No		
Mechanic's name: 56 Date: 16 / 19 / 22 Approved by: 56 Date: 16 / 19 / 32		
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A





Inventory CID: 73251	Vin #: 30395	Fair Market Value: \$ 250,00	
Short Description:			
Year: 2018 Make:Slammin Eagle Model: Curotto Can Mileage:			
This Vehicle: Starts Start	ts with a boost and 🔲 Runs 🔲 Doe.	s not Run For Parts Only	
Engine:L V	Gas Diesel Engine		
This Vehicle was maintained eve	ery Days Hours	Miles	
Condition: Runs Needs R	epair 🔲 ls in unknown condition		
Repairs Needed (Be specific):			
		_Est Cost of Repairs: \$	
Date removed from service:	// Maintenance I	Records: Avail Not Avail	
Transmission:			
Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
Minor Damage to: Major Damage to: 任しいよりは			
	Cold Unknown Air Bags: Dri		
Cruise Tilt Wheel Remot	e Mirrors Climate Ctr - PWR: Wind	ows Locks Steering Seats	
Exterior: Color Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4			
	Major Dents to:		
	s been removed $\Box_{ m t}$ here are holes in th		
Additional Equipment Description: MFG Model Serial #			
Lic Plates removed: Yes No ZONAR Removed: Yes No A/A			
Lights/ACC removed: Yes No N/A			
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No			
Mechanic's name: $\int \int Date: \int \int \int Date: \int \int \partial Date: \int \partial$			
Approved by: Date: Date: Date: Date: Date:			
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE:YESNON/A			





Inventory CID: 70133	Vin #: 1FDAF57P03RC90245	Fair Market Value: \$ 5,000	
Short Description:		•	
Year: <u>2003</u> Make: <u>FORD</u>	Model: <u>F550</u>	Mileage:	
	s with a boost and 🔲 Runs 🔲 Doe	s not Run For Parts Only	
Engine: 🔬 L V 🔲	Gas Diesel Engine		
This Vehicle was maintained eve	ery <u>3,000</u> Days Hours	Miles	
Condition: Runs Needs Ro	epair s in unknown condition	. 1/	
Repairs Needed (Be specific):	epair as in unknown condition Nexes engl	ne world	
		_Est Cost of Repairs: \$	
Date removed from service:	/ / Maintenance F	Records: Avail Not Avail	
Transmission:			
X Automatic Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
	Major Damage to		
	Cold Unknown Air Bags: Driv	The state of the s	
☑Cruise ☑Tilt Wheel □Remote Mirrors □Climate Ctr - PWR:□ Windows □Locks □Steering □Seats			
	idows: 📈 No cracked glass 🔀 Cracke		
Minor Dents Scratches Dings Tire Condition: Good Low Ital Hubcaps 1 2 3 4			
	Major Dents to:		
Emergency Equip: None Ha	s been removed \Box there are holes in th	ne exterior	
Additional Equipment Description		Serial #	
	o ZONAR Removed: ☐Yes ☐No ☐N/A	A	
Lights/ACC removed: Yes No N/A			
Fuel Card Turned in: XYes No Keys/KeyTrak Yes No Mechanic's name: Date: 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2 / 2			
Mechanic's name: Date: Date: Date:			
Approved by: Sc Date: $8/27/26$			
FOR PD VEHICLE: SEAT PUT BA	CK IN VEHICLE FROM STORAGE:	_YESNON/A	
Additional Comments:			





Inventory CID: 71222	Vin #: 1FTNF21598EB00851	Fair Market Value: \$ 1,000	
Short Description:			
Year: <u>2008</u> Make: <u>FORD</u>	Model: <u>F250</u>	Mileage:	
This Vehicle: Starts Start	s with a boost and 💢 Runs 🔲 Doe	s not Run For Parts Only	
Engine: <u>5.4</u> L V <u>\$\sqrt{2}</u>			
This Vehicle was maintained eve	ery <u>3000</u> Days Hours	Miles	
Condition: Runs Needs Re	epair		
Repairs Needed (Be specific):	lifter work, tailt	Est Cost of Repairs: \$	
		Est Cost of Repairs: \$	
Date removed from service:	// Maintenance	Records: Avail Not Avail	
Transmission:			
	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
	NONC.		
	witch plate Major Damage to		
	Cold Unknown Air Bags: Dri		
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR; Windows Locks Steering Seats			
Exterior: Color white Wir	ndows: No cracked glass Cracke	ed:	
Minor Dents Scratches Dings Tire Condition: Good Low Hat Hubcaps 1 2 3 4			
	Gate Major Dents to:		
	s been removed there are holes in t		
	,	Serial #	
Lic Plates removed: Yes No ZONAR Removed: Yes No N/A			
	No -N/ADEXTERIOR STOOP	· .	
Fuel Card Turned in: Yes	No Keys/KeyTrak XYes ☐ No	7	
Mechanic's name:	Date: 8/27/22	<u>_</u>	
	Date: 8 / 17 22		
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE:YESNON/A			





Inventory CID: 70554	Vin #: CAT00304ENAD02603	Fair Market Value: \$	
Short Description:		Hairs	
Year: 2005 Make: Caterpillar	Model: <u>Excavator 304</u>	Hours Mileage: 2327	
This Vehicle: Starts Start	s with a boost and 🔲 Runs 📈 Does		
Engine:L V_ <u></u>	Gas Diesel Engine		
This Vehicle was maintained eve	ery 250 Days Hours	Miles	
Repairs Needed (Be specific):	epair	Engine Blown	
		_Est Cost of Repairs: \$	
Date removed from service:	/ / Maintenance F	Records: Avail Not Avail	
Transmission:			
Automatic 🔲 Manual	Condition is: Operable Needs Re	pair 🔲 Is Unknown	
Transmission repairs needed:			
	Major Damage to:		
AC No AC AC Condition:	□Cold □Unknown Air Bags: □Driv	ver's Side Dual	
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats			
Exterior: Color /// Windows: No cracked glass Cracked:			
Minor Dents Scratches Dings Tire Condition: Good Low I lat Uhubcaps 1 2 3 4			
Minor Dents to:	Major Dents to:	NONC	
Emergency Equip None Ha	s been removed \Box there are holes in th	ne exterior There are no holes	
Additional Equipment Description	on: MFG Model	Serial #	
Lic Plates removed; ✓Yes ☐No ZONAR Removed: ✓Yes ☐No ☐N/A			
Lights/ACC removed: No N/A Fuel Card Turned in: Yes No Keys/KeyTrak Yes No - Cct Key Mechanic's name: Date: 4 3 32. Approved by: Date: Date:			
Fuel Card Turned in: XYes	No Keys/KeyTrak XYes ☐ No	- ccit Key	
Mechanic's name: \(\sum_{\text{om}}\)	10K Date: 9/3/2	<u>-</u>	
Approved by:	/ Date://		
FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: YES NO N/A			
Additional Comments	ai .		