



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71938 Vin #: 1FAHP2L82EG129650 Fair Market Value: \$ 8500.00

Short Description:

Year: 2014 Make: Ford Model: Taurus Mileage: 55850.

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: 3.5 L V 6 Gas Diesel Engine

This Vehicle was maintained every 5000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): _____

Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color Black Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Tom Lyon Date: 11/12/2020

Approved by: _____ Date: 11/12/20

Additional Comments: Very Minor Dents and Scratches



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 72942 Vin #: 2G1WD5E35G1162874 Fair Market Value: \$ 2500.00

Short Description:

Year: 2016 Make: Chevy Model: Impala Mileage: 27627

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: 3.6L V6 Gas Diesel Engine

This Vehicle was maintained every 5000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): _____

Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color Black Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed there are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Tom Lyon Date: 11 / 12 / 2020

Approved by: [Signature] Date: 11 / 12 / 20

Additional Comments:

Minor scratches to hood and left Rear quarter also deck lid.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71608 Vin #: 1GNLC2E09BR286915 Fair Market Value: \$ 2500.00

Short Description:

Year: 2011 Make: Chevy Model: Tahoe Mileage: 40 96989

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: 5.3L V8 Gas Diesel Engine

This Vehicle was maintained every 3000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): _____

Est Cost of Repairs: \$ _____

Date removed from service: ___/___/_____ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: left Rear door Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color White Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: left Rear door Major Dents to: _____

Emergency Equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Tom Lyon Date: 11/12/2020

Approved by: [Signature] Date: 11/12/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>05515</u>	Vin #: <u>5JG-0214981</u>	Fair Market Value: \$ <u>100.00</u>
Short Description: Year: <u>94</u> Make: <u>Cose</u> Model: <u>Forklift</u> Mileage: <u>1393H</u>		
This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only Engine: ___ L V ___ <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine <u>4-390</u> This Vehicle was maintained every <u>250</u> <input type="checkbox"/> Days <input checked="" type="checkbox"/> Hours <input type="checkbox"/> Miles Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition Repairs Needed (Be specific): _____ Est Cost of Repairs: \$ _____		
Date removed from service: ___/___/___ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission: <input type="checkbox"/> Automatic <input checked="" type="checkbox"/> Manual Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown Transmission repairs needed: _____		
Minor Damage to: <u>Seat</u> Major Damage to: _____ <input type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input checked="" type="checkbox"/> Seats		
Exterior: Color <u>yellow</u> Windows: <input type="checkbox"/> No cracked glass Cracked: _____ Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 Minor Dents to: _____ Major Dents to: _____ Emergency Equip: <input checked="" type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG <u>Cose</u> Model <u>S86E</u> Serial # <u>JJG0131096</u>		
Lic Plates removed: <input type="checkbox"/> Yes <input type="checkbox"/> No ZONAR Removed: <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> N/A		
Lights/ACC removed: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No N/A		
Fuel Card Turned in: <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No Keys/KeyTrak <input type="checkbox"/> Yes <input type="checkbox"/> No		
Mechanic's name: <u>Tom Lyon</u> Date: <u>11/12/2020</u>		
Approved by: <u>SL</u> Date: <u>11/12/20</u>		

Additional Comments:

Front Hyd cylinders leak. Rusty and sun faded



**CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM**



Inventory CID: 71290 Vin #: _____ Fair Market Value: \$ 250.00

Short Description:

Year: 2007 Make: Nite/ike Model: Tower Mileage: _____

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: _____ L V _____ Gas Diesel Engine

This Vehicle was maintained every 6 months Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): Does not supply electricity
Est Cost of Repairs: \$ _____

Date removed from service: ____/____/____ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color _____ Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: SL Date: 1/15/21

Approved by: SL Date: 1/15/21

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 73345 Vin #: _____ Fair Market Value: \$ 1500.00

Short Description:

Year: 2010 Make: SkyWatch Model: Trailer Mileage: _____

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: ___ L V ___ Gas Diesel Engine

This Vehicle was maintained every 600 hrs Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): Lift cylinder pistons are rusted

Est Cost of Repairs: \$ _____

Date removed from service: ___ / ___ / _____ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color White Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: SC Date: 1/15/21

Approved by: SL Date: 1/15/21

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 72310	Vin #: _____	Fair Market Value: \$ <u>200.00</u>
Short Description: Year: _____ Make: <u>40y</u> Model: <u>Roll off box</u> Mileage: _____		
This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input checked="" type="checkbox"/> For Parts Only Engine: _____ L V _____ <input type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine This Vehicle was maintained every _____ <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition Repairs Needed (Be specific): _____ Est Cost of Repairs: \$ _____		
Date removed from service: ____/____/____ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____ <input type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual <input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color <u>Body</u> Windows: <input type="checkbox"/> No cracked glass Cracked: _____ Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good <input type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 Minor Dents to: _____ Major Dents to: <u>Everything</u> Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input checked="" type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: SL Date: 1/15/21

Approved by: SL Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: _____ YES _____ NO _____ N/A

Additional Comments:

Box and door dented and damaged.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>0507A</u>	Vin #: _____	Fair Market Value: \$ <u>500'00</u>
Short Description: Year: <u>93</u> Make: <u>Atlas</u> Model: <u>Compressor</u> Mileage: _____		
This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only		
Engine: _____ L V _____ <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>6 months</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input type="checkbox"/> Miles		
Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): <u>Old and worn out but runs at this time</u>		
Est Cost of Repairs: \$ _____		
Date removed from service: ___/___/___ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission: <input type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____		
<input type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual		
<input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color _____ Windows: <input type="checkbox"/> No cracked glass Cracked: _____		
Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: CC Date: 1/15/21

Approved by: ED Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: _____ YES _____ NO _____ N/A

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 72409 Vin #: _____ Fair Market Value: \$ 8000 wo

Short Description:

Year: 2014 Make: Autar Model: Side loader Mileage: 10600

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: ___ L V ___ Gas Diesel Engine

This Vehicle was maintained every 6000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): _____

Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color white Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: GL Date: 1/15/21

Approved by: [Signature] Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: ___ YES ___ NO ___ N/A

Additional Comments:

Oil and hyd leaks. Arm and grabber assembly very worn



**CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM**



Inventory CID: <u>70494</u>	Vin #: _____	Fair Market Value: \$ <u>800.00</u>
Short Description: Year: <u>2014</u> Make: <u>Autocars</u> Model: <u>Front loader</u> Mileage: <u>84,000</u>		
This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input checked="" type="checkbox"/> For Parts Only		
Engine: _____ L V _____ <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>6000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Condition: <input type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): _____		
Est Cost of Repairs: \$ _____		
Date removed from service: ____/____/____ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____		
<input type="checkbox"/> AC <input checked="" type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual		
<input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color <u>White</u> Windows: <input type="checkbox"/> No cracked glass Cracked: _____		
Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: gl Date: 1/15/21

Approved by: gl Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: _____ YES _____ NO _____ N/A

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>71620</u>	Vin #: _____	Fair Market Value: \$ <u>8000⁰⁰⁰</u>
Short Description: Year: <u>2011</u> Make: <u>Autocross</u> Model: <u>Side Loader</u> Mileage: <u>132,000</u>		
This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only		
Engine: _____ L V _____ <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>600,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): _____		
Est Cost of Repairs: \$ _____		
Date removed from service: ___/___/_____ Maintenance Records: <input type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission: <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____		
<input type="checkbox"/> AC <input checked="" type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input checked="" type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual		
<input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color <u>White</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____		
Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: [Signature] Date: 1/15/21

Approved by: [Signature] Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: _____ YES _____ NO _____ N/A

Additional Comments:

Numerous leaks. Gaskets worn and claw very worn.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71601 ~~21601~~ Vin #: _____ Fair Market Value: \$ 8000 ^{and}

Short Description:
 Year: 2011 Make: Autocar Model: Side Loader Mileage: ~~133,000~~ 133,000

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
 Engine: ___ L V ___ Gas Diesel Engine
 This Vehicle was maintained every 6000 Days Hours Miles
 Condition: Runs Needs Repair Is in unknown condition
 Repairs Needed (Be specific): _____ Est Cost of Repairs: \$ _____

Date removed from service: ___ / ___ / _____ Maintenance Records: Avail Not Avail

Transmission:
 Automatic Manual Condition is: Operable Needs Repair Is Unknown
 Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____
 AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
 Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color White Windows: No cracked glass Cracked: _____
 Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4
 Minor Dents to: _____ Major Dents to: _____
 Emergency Equip: None Has been removed There are holes in the exterior There are no holes
 Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Loz Date: 1 / 15 / 21

Approved by: [Signature] Date: 1 / 15 / 21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: ___ YES ___ NO ___ N/A

Additional Comments:

Numerous engine oil and hydraulic leaks. ~~Claw~~ Grabber arm and claw very worn.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71622 Vin #: _____ Fair Market Value: \$ 8,000⁰⁰⁰

Short Description:
 Year: 11 Make: Autocor Model: Side loader Mileage: 122,000

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: ___ L V ___ Gas Diesel Engine

This Vehicle was maintained every 6000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): All ~~the~~ hydraulics and mechanical body components very worn out. Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:
 Automatic Manual Condition is: Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: Dents/dings/scratches Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color _____ Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed there are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: JK Date: 1/15/21

Approved by: JK Date: 1/15/21

FOR PD VEHICLE: SEAT PUT BACK IN VEHICLE FROM STORAGE: ___ YES ___ NO ___ N/A

Additional Comments:
Oil, hyd leaks. No claw