

Asset Disposition and Recommended Method

SEPTEMBER 25 2018

CID #	YEAR	Description	DEPT	Mileage/Hours	Condition	Reason for Disposal	Method of Disposal	Estimated Value	COMMISSION APPROVAL
71783	2013	2013 FORD INTERCEPTOR SEDAN- UNMARKED- SN 1FAHP2L81DG152755	PD	83138	GOOD/FAIR	OBSOLETE	SALE TO SRQ PROGRAM	\$ 6,000.00	
71932	2014	2014 FORD INTERCEPTOR SEDAN- MARKED- SN 1FAHP2L84EG127799	PD	46622	GOOD/FAIR	OBSOLETE	SALE TO SRQ PROGRAM	\$ 6,500.00	
71933	2014	2014 FORD INTERCEPTOR SEDAN- MARKED- SN 1FAHP2L87EG127800	PD	47327	GOOD/FAIR	OBSOLETE	SALE TO SRQ PROGRAM	\$ 6,500.00	
71936	2014	2014 FORD INTERCEPTOR SEDAN- MARKED- SN 1FAHP2L82EG127803	PD	50802	GOOD/FAIR	OBSOLETE	SALE TO SRQ PROGRAM	\$ 6,500.00	

CITY OF NORTH PORT
PROPERTY DISPOSAL FORM



DEPARTMENT SUBMITTED BY: PW for PD

DATE: Aug 20th 2018

Overthreshold Item(s) \$5,000.00+

Underthreshold Item(s) < \$5,000.00

ITEM DESCRIPTION					REASON FOR DISPOSAL SELECT ONE OPTION (X)						SELECT ONE METHOD OF DISPOSAL (X)				
ITEM YEAR	ITEM DESCRIPTION (Make, Model, Serial, VIN# & Mileage)	DATE OF PURCHASE/ COST	CITY PERIPHERAL ID NUMBER	CURRENT ITEM CONDITION	OBSOLETE	LOST/ STOLEN	SCRAP	SURPLUS AUCTION / DONATION	TRADED IN	PER REPLACEMENT POLICY	AUCTION	DONATION	SCRAP	STOLEN/LOST	TRADED IN
2013	Ford Interceptor	1/30/2013	71783	Fair											
	1FAHP2L81DG152755	\$ 25,237.00													
2014	Ford Interceptor	4/4/2014	71932	Fair											
	1FAHP2L84EG127799	\$ 42,371.00													
2014	Ford Interceptor	4/4/2014	71933	Fair											
	1FAHP2L87EG127800	\$ 42,371.00													
2014	Ford Interceptor	4/4/2014	71936	Fair											
	1FAHP2L82EG127803	\$ 42,371.00													

Per the code of the City of North Port, Florida:

Assets with an original purchase value greater than the threshold limit set forth, must receive City Commission approval for disposal and then may be disposed of (BY FINANCE) in an appropriate fashion

Fleet Approved

By signing this form, I attest that due diligence has been performed and proper procedures have been followed as outlined in the Code of the City of North Port Florida prior to this/these disposal(s). I accept full responsibility for this action.

By signing this form, I attest that the required information necessary for the proper disposal of said asset(s) has been received.

DEPARTMENT DIRECTOR [Signature] DATE 8/23/18

Approval Initial: [Signature]

FINANCE DIRECTOR [Signature] DATE 08/20/18

FIXED ASSET CUSTODIAN [Signature] DATE 8.24.18

Date: 8/20/18

CITY MANAGER _____ DATE _____

CHAIN OF COMMAND

(This form must be attached to all correspondence sent through the Chain of Command)

Subject: Sale of fleet vehicles to Sarasota County School Board Police

From: Captain King Date: 8/22/18

- Approved
 Not approved
 For your approval
 Review & advise
 Discuss with me
 Prepare response for my signature
 Prepare response for your signature
 Copy me
 File
 FYI
 Schedule a meeting with _____
 For investigation
 For inquiry
 Other

Comments: This needs to be signed by the director and returned to Steve Hauser at fleet.

Due date: _____

Forward to: D/C Morales cc: Chief Garrison

From: _____ Date: _____

- Approved
 Not approved
 For your approval
 Review & advise
 Discuss with me
 Prepare response for my signature
 Prepare response for your signature
 Copy me
 File
 FYI
 Schedule a meeting with _____
 For investigation
 For inquiry
 Other

Comments:

Due date: _____

Forward to: _____ cc: _____

From: _____ Date: _____

- Approved
 Not approved
 For your approval
 Review & advise
 Discuss with me
 Prepare response for my signature
 Prepare response for your signature
 Copy me
 File
 FYI
 Schedule a meeting with _____
 For investigation
 For inquiry
 Other

Comments:

Due date: _____

Forward to: _____ cc: _____



GovDeals Equipment Inspection Form

Inventory ID: <u>71932</u>	Asset Number	Fair Market Value: <u>5600</u>
----------------------------	--------------	--------------------------------

Short Description:
 Year 2014 Manufacturer Ford 46700 Model Taurus

Please fill in or check **Long Description:**

This Equipment: Starts Starts with a Boost & Is Operable Is not operable For Parts Only

Engine L, V 6 Gas Diesel engine Hours _____ Miles _____

This vehicle was maintained every 4000 Hours Mile

Engine Manufacture: _____ **Condition:** Is Operable Needs repair Is in Unknown Condition

Repairs needed: _____

Note: Equipment & Engine condition stated at time of inspection

Transmission

Transmission: Automatic Manual _____ Speed Transmission: Hours _____ Miles _____

Transmission Manufacture: _____ **Condition:** Is Operable Needs Repair Is Unknown

Repairs Needed: _____

Note: Transmission condition stated at time of inspection

Interior: Color Black Cloth Vinyl Leather

Minor damage to: _____

Major damage to: _____

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

Cruise Control Power: Steering Seats AC No AC Condition: Cold Unknown

Note: A/C condition stated at time of inspection

Exterior: Color Black White Windows: No cracked glass Cracked _____

Minor Dents Scratches Dings Tire Condition: Low _____ Flat _____

Minor dents to: _____

Major damage to: _____

Of Wheels _____ # Of Axles _____ # Of Tracks _____

Dimensions: _____

Decals: None Have been sprayed Have been removed Impressions remain No impressions

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Is in Unknown Condition

Description: PD Equipped - Radar / Radio

License Plate removed: Fuel Card removed:

Note: Additional equipment condition stated at time of inspection

Location of Asset: _____

For more information contact: _____

Date Inspected: _____ Inspected by: _____

GovDeals Equipment Inspection Form

Inventory ID: <u>71783</u>	Asset Number	Fair Market Value: <u>4500</u>
----------------------------	--------------	--------------------------------

Short Description:
 Year 2013 Manufacturer Ford 84000 Model Taurus

Please fill in or check **Long Description:**

This Equipment: Starts Starts with a Boost & Is Operable Is not operable For Parts Only

Engine L, V 6 Gas Diesel engine Hours _____ Miles _____

This vehicle was maintained every 4000 Hours Miles

Engine Manufacture: _____ Condition: Is Operable Needs repair Is in Unknown Condition

Repairs needed: _____

Note: Equipment & Engine condition stated at time of inspection

Transmission

Transmission: Automatic Manual Speed _____ Transmission: _____ Hours _____ Miles _____

Transmission Manufacture: _____ Condition: Is Operable Needs Repair Is Unknown

Repairs Needed: _____

Note: Transmission condition stated at time of inspection

Interior: Color Black Cloth Vinyl Leather

Minor damage to: _____

Major damage to: _____

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

Cruise Control Power: Steering Seats AC No AC Condition: Cold Unknown

Note: A/C condition stated at time of inspection

Exterior: Color Gold Windows: No cracked glass Cracked _____

Minor Dents Scratches Dings Tire Condition: Low Flat _____

Minor dents to: _____

Major damage to: _____

Of Wheels _____ # Of Axles _____ # Of Tracks _____

Dimensions: _____

Decals: None Have been sprayed Have been removed Impressions remain No impressions

Additional Equipment: Manufacturer _____ Model _____

Serial # _____ Condition: Is Operable Needs repair Is in Unknown Condition

Description: PDE equipped interior, unmarked exterior

License Plate removed: Fuel Card removed:

Note: Additional equipment condition stated at time of inspection

Location of Asset: _____

For more information contact: _____

Date Inspected: _____ Inspected by: _____

Auction Vehicle Inspection Form

Inventory ID <u>71933</u>	Asset Number _____	Fair Market Value: <u>5600</u>
---------------------------	--------------------	--------------------------------

Short Description:
 Year 2014 Make Ford 47420 Model Taurus

Please fill in or check **Long Description:**

This vehicle: Starts Starts with a boost and Runs Does not run For Parts Only

Engine L, V 6 Gas Diesel engine

This vehicle was maintained every 9000 Days Hours Miles

Condition: Runs Needs repair is in unknown condition

Repairs needed: _____

Date Removed From Service: _____ Maintenance Records: Available Not Available

Transmission

Transmission: Automatic Manual _____ Speed **Condition**

is: Operable Needs repair Is Unknown

Repairs Needed: _____

Interior: Color Black Cloth Vinyl Leather

Minor damage to: _____

Major damage to: _____

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

AC No AC Condition: Cold Unknown Air Bags drivers side dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Windows Door Locks Steering Seats

Exterior: Color Black/white Windows: No cracked glass cracked _____

Minor Dents Scratches Dings Tire Condition: Low _____ Flat _____ Hubcaps 1 2 3 4

Minor dents to: _____

Major damage to: _____

Decals: None Have been sprayed Have been removed Impressions remain No impressions

Emergency equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment: Description PD Equipped

Manufacturer _____ Model _____ Serial # _____

Vehicle Info: VIN # _____ Mileage _____ Title Restriction Y N

ZONAR Removed? Y N N/A Lights/ACCs removed? Y N N/A Decals Removed? Y N N/A

For more information contact: _____

Dept Head Print: _____ **Dept Head Signature:** _____ **Date:** ___/___/___

Auction Vehicle Inspection Form

Inventory ID 71936	Asset Number	Fair Market Value: 5000
Short Description: Year <u>2014</u> Make <u>Ford</u> <u>50936</u> Model <u>Taurus</u>		

Please fill in or check **Long Description:**

This vehicle: Starts Starts with a boost and Runs Does not run For Parts Only

Engine L, V 6 Gas Diesel engine

This vehicle was maintained every 4000 Days Hours Miles

Condition: Runs Needs repair is in unknown condition

Repairs needed: _____

Date Removed From Service: _____ Maintenance Records: Available Not Available

Transmission

Transmission: Automatic Manual Speed Condition _____

is: Operable Needs repair Is Unknown

Repairs Needed: _____

Interior: Color Black Cloth Vinyl Leather

Minor damage to: _____

Major damage to: _____

Radio: Brand _____ AM AM/FM AM/FM Cassette AM/FM CD

AC No AC Condition: Cold Unknown Air Bags drivers side dual

Cruise Control Tilt Steering Remote Mirrors Climate Control

Power: Windows Door Locks Steering Seats

Exterior: Color Black/white Windows: No cracked glass cracked _____

Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 1 2 3 4

Minor dents to: _____

Major damage to: _____

Decals: None Have been sprayed Have been removed Impressions remain No impressions

Emergency equip: None Has been removed There are holes in the exterior There are no holes

Additional Equipment: Description FP Equipment - Tires and Radio

Manufacturer _____ Model _____ Serial # _____

Vehicle Info: VIN # _____ Mileage _____ Title Restriction Y N

ZONAR Removed? Y N N/A Lights/ACCs removed? Y N N/A Decals Removed? Y N N/A

For more information contact: _____

Dept Head Print: _____ Dept Head Signature: _____ Date: ___/___/___