



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>71390</u>	Vin #: <u>1HTWXAHR39J126670</u>	Fair Market Value: \$ <u>18,000.00</u>
Short Description:		
Year: <u>2009</u> Make: <u>Int</u> Model: <u>Dump work star</u> Mileage: <u>199,001</u>		
This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only		
Engine: <u> </u> L V <u> </u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>7500</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): _____		
Est Cost of Repairs: \$ _____		
Date removed from service: <u>8/13/2020</u> Maintenance Records: <input type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission:		
<input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission repairs needed: _____		
Minor Damage to: <u>REAR Dump body</u> Major Damage to: _____		
<input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input type="checkbox"/> Dual		
<input checked="" type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR <input type="checkbox"/> Windows <input type="checkbox"/> Locks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color <u>white</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____		
Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input type="checkbox"/> Low <input type="checkbox"/> Flat Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip <input type="checkbox"/> None <input checked="" type="checkbox"/> Has been removed <input type="checkbox"/> there are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A
 Lights/ACC removed: Yes No N/A
 Fuel Card Turned in: Yes No Keys/KeyTrak Yes No
 Mechanic's name: Gary Stutch Date: 8/13/20
 Approved by: [Signature] Date: 8/13/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71253 Vin #: 55VBT191671001732 Fair Market Value: \$ 400⁰⁰

Short Description:
 Year: 2007 Make: _____ Model: Centerville Trailer Mileage: _____

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
 Engine: _____ L V _____ Gas Diesel Engine
 This Vehicle was maintained every _____ Days Hours Miles
 Condition: Runs Needs Repair Is in unknown condition
 Repairs Needed (Be specific): _____

Est Cost of Repairs: \$ _____

Date removed from service: ____/____/____ Maintenance Records: Avail Not Avail

Transmission:
 Automatic Manual Condition is: Operable Needs Repair Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: Front end deck were rotted

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
 Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color _____ Windows: No cracked glass Cracked: _____
 Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: _____

Emergency Equip: None Has been removed there are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Steve C. Date: 11/3/20

Approved by: SL Date: 11/3/20

Additional Comments: LARGE AMOUNTS OF RUST & HOLES.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 73185 Vin #: LFTR3XMS5KA3276 Fair Market Value: \$ 100.00

Short Description:
Year: 18 Make: Ford Model: Transit Mileage: 16253

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only

Engine: L V6 Gas Diesel Engine

This Vehicle was maintained every 4000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): Rear end collision Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:

Automatic Manual Condition is Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____

AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual

Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color _____ Windows: No cracked glass Cracked: _____

Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 2 3 4

Minor Dents to: _____ Major Dents to: Rear end, accident.

Emergency Equip: None Has been removed there are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Steve C Date: 11/3/20

Approved by: [Signature] Date: 11/3/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 72903 Vin #: 1FM5K8AP066050301 Fair Market Value: \$ 1000

Short Description:
Year: 2016 Make: Ford Model: Explorer PD Mileage: 71853

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
Engine: 6 L V 6 Gas Diesel Engine

This Vehicle was maintained every 5000 Days Hours Miles

Condition: Runs Needs Repair Is in unknown condition

Repairs Needed (Be specific): Foundered in car accident. Est Cost of Repairs: \$ _____

Date removed from service: ___/___/___ Maintenance Records: Avail Not Avail

Transmission:
 Automatic Manual Condition is Operable Needs Repair Is Unknown

Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: _____
 AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
 Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color Blk/Wht Windows: No cracked glass Cracked: _____
Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 1 2 3 4

Minor Dents to: _____ Major Dents to: Front end

Emergency Equip None Has been removed there are holes in the exterior There are no holes

Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Steve C Date: 11/3/20

Approved by: [Signature] Date: 11/3/20

Additional Comments: Some emergency equipment has been removed.



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>71310</u>	Vin #: <u>1F DAF 57R78E48913</u>	Fair Market Value: \$ <u>6000⁰⁰</u>
Short Description:		
Year: <u>08</u> Make: <u>Ford</u> Model: <u>F-550</u> Mileage: <u>151984</u>		
This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input checked="" type="checkbox"/> For Parts Only		
Engine: <u>L V8</u> <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>4000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Condition: <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): <u>High pressure fuel pump malfunction, needs replaced.</u>		
Est Cost of Repairs: \$ <u>10,000</u>		
Date removed from service: ___/___/___ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission:		
<input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Unknown		
Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____		
<input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input checked="" type="checkbox"/> Driver's Side <input type="checkbox"/> Dual		
<input checked="" type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input checked="" type="checkbox"/> Windows <input type="checkbox"/> Locks <input type="checkbox"/> Steering <input type="checkbox"/> Seats		
Exterior: Color <u>White</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____		
Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat Hubcaps 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: [Signature] Date: 11 / 3 / 20

Approved by: [Signature] Date: 11 / 3 / 20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
 FLEET MANAGEMENT DIVISION
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 72311 / ~~73711~~ Vin #: _____ Fair Market Value: \$ 400.00

Short Description: _____
 Year: _____ Make: 40y Model: Roll off Container Mileage: _____

This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
 Engine: _____ L V _____ Gas Diesel Engine
 This Vehicle was maintained every _____ Days Hours Miles
 Condition: Runs Needs Repair Is in unknown condition
 Repairs Needed (Be specific): _____
 _____ Est Cost of Repairs: \$ _____

Date removed from service: ____/____/____ Maintenance Records: Avail Not Avail

Transmission:
 Automatic Manual Condition is: Operable Needs Repair Unknown
 Transmission repairs needed: _____

Minor Damage to: _____ Major Damage to: Frame and sides are rotted out
 AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
 Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR: Windows Locks Steering Seats

Exterior: Color Rust Windows: No cracked glass Cracked: _____
 Minor Dents Scratches Dings Tire Condition: Good Low Flat Hubcaps 1 2 3 4
 Minor Dents to: _____ Major Dents to: Everything
 Emergency Equip None Has been removed There are holes in the exterior There are no holes
 Additional Equipment Description: MFG _____ Model _____ Serial # _____

Lic Plates removed: Yes No ZONAR Removed: Yes No N/A
 Lights/ACC removed: Yes No N/A
 Fuel Card Turned in: Yes No Keys/KeyTrak Yes No
 Mechanic's name: Steve C Date: 11/3/20
 Approved by: [Signature] Date: 11/3/20

Additional Comments: Completely rotted out, unusable

SW 40YD Roll off Container



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT
FLEET MANAGEMENT DIVISION
MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: <u>72476</u>	Vin #: <u>2G1WD5E37E1184834</u>	Fair Market Value: \$ <u>\$5000</u>
Short Description:		
Year: <u>2014</u> Make: <u>Chevy</u> Model: <u>Impala</u> Mileage: <u>22280</u>		
This Vehicle: <input type="checkbox"/> Starts <input checked="" type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only		
Engine: <u>3.6</u> L V <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine		
This Vehicle was maintained every <u>5,000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles		
Condition: <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition		
Repairs Needed (Be specific): _____		
Est Cost of Repairs: \$ _____		
Date removed from service: ____/____/____ Maintenance Records: <input type="checkbox"/> Avail <input type="checkbox"/> Not Avail		
Transmission:		
<input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown		
Transmission repairs needed: _____		
Minor Damage to: _____ Major Damage to: _____		
<input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual		
<input checked="" type="checkbox"/> Cruise <input checked="" type="checkbox"/> Tilt Wheel <input checked="" type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Locks <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Seats		
Exterior: Color <u>Black = white</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____		
Minor <input type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input checked="" type="checkbox"/> 4		
Minor Dents to: _____ Major Dents to: _____		
Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> there are holes in the exterior <input type="checkbox"/> There are no holes		
Additional Equipment Description: MFG _____ Model _____ Serial # _____		

Lic Plates removed: Yes No ZONAR Removed Yes No N/A

Lights/ACC removed: Yes No N/A

Fuel Card Turned in: Yes No Keys/KeyTrak Yes No

Mechanic's name: Matt Moore Date: 1/23/19

Approved by: [Signature] Date: 9/4/19

Additional Comments:

VEHICLE STINKS! - Strong smell from vents at times.

Has had many issues under warranty. Stalling, trans slip etc.

Vehicle runs and drives at this time.