



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



|  |                           |   |
|--|---------------------------|---|
| Inventory CID: <u>03446</u>  | Vin #: <u>F311011</u>     | Fair Market Value: <u>\$500<sup>max</sup></u> |
| Short Description:   |                           |   |
| Year: <u>1994</u> Make: <u>Thompson</u> Model: <u>4HT-296</u>  | Mileage: <u>742.9 hrs</u> |   |
| This Vehicle: <input type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only  |                           |   |
| Engine: <input type="checkbox"/> L <input type="checkbox"/> V <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine   |                           |   |
| This Vehicle was maintained every _____ <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles   |                           |   |
| Condition: <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition   |                           |   |
| Repairs Needed (Be specific): <u>Will not start Deutz engine</u>   |                           |   |
| Est Cost of Repairs: \$ _____  |                           |   |
| Date removed from service: ___/___/___ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> Not Avail   |                           |   |
| Transmission:  |                           |   |
| <input type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input checked="" type="checkbox"/> Unknown   |                           |   |
| Transmission repairs needed: _____   |                           |   |
| Minor Damage to: _____ Major Damage to: _____  |                           |   |
| <input type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual  |                           |   |
| <input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input checked="" type="checkbox"/> Locks <input checked="" type="checkbox"/> Steering <input checked="" type="checkbox"/> Seats                              |                           |   |
| Exterior: Color <u>Blue</u> Windows: <input type="checkbox"/> No cracked glass Cracked: _____  |                           |   |
| Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: <input checked="" type="checkbox"/> Good <input type="checkbox"/> Low <input type="checkbox"/> Flat Hubcaps 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 |                           |   |
| Minor Dents to: <u>Faded paint</u> Major Dents to: _____   |                           |   |
| Emergency Equip: <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> There are holes in the exterior <input type="checkbox"/> There are no holes  |                           |   |
| Additional Equipment Description: MFG _____ Model _____ Serial # _____   |                           |   |

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A

Lights/ACC removed:  Yes  No N/A

Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No

Mechanic's name: Matt Moore Date: 11/15/20

Approved by: [Signature] Date: 11/16/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 70517 Vin #: 1FMFU1658SLA650 Fair Market Value: \$ 1,000

Short Description:  
 Year: 2005 Make: Ford Model: Expedition Mileage: 153,034

This Vehicle:  Starts  Starts with a boost and  Runs  Does not Run  For Parts Only  
 Engine: 5.4 L V8  Gas  Diesel Engine  
 This Vehicle was maintained every 5,000  Days  Hours  Miles  
 Condition:  Runs  Needs Repair  Is in unknown condition  
 Repairs Needed (Be specific): Transmission Bad only HAS REVERSE ONLY  
 Est Cost of Repairs: \$ \_\_\_\_\_

Date removed from service: 2/13/2020 Maintenance Records:  Avail  Not Avail

Transmission:  
 Automatic  Manual Condition is:  Operable  Needs Repair  Unknown  
 Transmission repairs needed: \_\_\_\_\_

Minor Damage to: \_\_\_\_\_ Major Damage to: \_\_\_\_\_  
 AC  No AC AC Condition:  Cold  Unknown Air Bags:  Driver's Side  Dual  
 Cruise  Tilt Wheel  Remote Mirrors  Climate Ctr - PWR:  Windows  Locks  Steering  Seats

Exterior: Color White Windows:  No cracked glass Cracked: \_\_\_\_\_  
 Minor  Dents  Scratches  Dings Tire Condition: Good  Low  Flat Hubcaps 1  2  3  4  
 Minor Dents to: \_\_\_\_\_ Major Dents to: \_\_\_\_\_  
 Emergency Equip:  None  Has been removed  There are holes in the exterior  There are no holes  
 Additional Equipment Description: MFG \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A  
 Lights/ACC removed:  Yes  No N/A  
 Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No  
 Mechanic's name: Brad Orlando Date: 2/13/2020  
 Approved by: [Signature] Date: 2/15/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



|  |                                |  |
|--|--------------------------------|--|
| Inventory CID: <u>71201</u>  | Vin #: <u>1FD5W5G07EA26028</u> | Fair Market Value: \$ <u>5000<sup>00</sup></u> |
| Short Description:   |                                |  |
| Year: <u>07</u> Make: <u>F-550</u> Model: _____ Mileage: <u>103034</u>   |                                |  |
| This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only   |                                |  |
| Engine: _____ L V _____ <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Diesel Engine   |                                |  |
| This Vehicle was maintained every <u>5000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles   |                                |  |
| Condition: <input type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs Repair <input checked="" type="checkbox"/> Is in unknown condition  |                                |  |
| Repairs Needed (Be specific): <u>one missing on several cylinders</u>  |                                |  |
| Est Cost of Repairs: \$ <u>1200<sup>00</sup></u>   |                                |  |
| Date removed from service: ____/____/____ Maintenance Records: <input checked="" type="checkbox"/> Avail <input type="checkbox"/> NOT Avail  |                                |  |
| Transmission:  |                                |  |
| <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is: <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input checked="" type="checkbox"/> Unknown   |                                |  |
| Transmission repairs needed: _____   |                                |  |
| Minor Damage to: <u>Faded, dents, dings etc</u> Major Damage to: _____   |                                |  |
| <input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Cold <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual  |                                |  |
| <input type="checkbox"/> Cruise <input type="checkbox"/> Tilt Wheel <input type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR: <input type="checkbox"/> Windows <input checked="" type="checkbox"/> Locks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats |                                |  |
| Exterior: Color <u>white</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____  |                                |  |
| Minor <input type="checkbox"/> Dents <input type="checkbox"/> Scratches <input type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> New <input type="checkbox"/> Flat Hubcaps 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4                   |                                |  |
| Minor Dents to: _____ Major Dents to: _____  |                                |  |
| Emergency Equip <input type="checkbox"/> None <input type="checkbox"/> Has been removed <input type="checkbox"/> there are holes in the exterior <input type="checkbox"/> There are no holes   |                                |  |
| Additional Equipment Description: MFG <u>Utility bed</u> Model _____ Serial # _____  |                                |  |

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A  
 Lights/ACC removed:  Yes  No N/A  
 Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No  
 Mechanic's name: mat H. Date: 3/23/10  
 Approved by: [Signature] Date: 3/23/10

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 70681 Vin #: 1FTRX14516KB20409 Fair Market Value: \$ 2500.00

Short Description:  
 Year: 2006 Make: Ford Model: F150 4x4 Mileage: 104726

This Vehicle:  Starts  Starts with a boost and  Runs  Does not Run  For Parts Only  
 Engine: 5.4 L V 8  Gas  Diesel Engine

This Vehicle was maintained every 5000  Days  Hours  Miles  
 Condition:  Runs  Needs Repair  Is in unknown condition

Repairs Needed (Be specific): \_\_\_\_\_  
 Est Cost of Repairs: \$ \_\_\_\_\_

Date removed from service: \_\_\_/\_\_\_/\_\_\_ Maintenance Records:  Avail  Not Avail

Transmission:  
 Automatic  Manual Condition is  Operable  Needs Repair  Is Unknown  
 Transmission repairs needed: \_\_\_\_\_

Minor Damage to: \_\_\_\_\_ Major Damage to: \_\_\_\_\_  
 AC  No AC AC Condition:  Cold  Unknown Air Bags:  Driver's Side  Dual  
 Cruise  Tilt Wheel  Remote Mirrors  Climate Ctr - PWR  Windows  Locks  Steering  Seats

Exterior: Color white Windows:  No cracked glass Cracked: \_\_\_\_\_  
 Minor  Dents  Scratches  Dings Tire Condition:  Low  Flat Hubcaps  2  3  4

Minor Dents to: \_\_\_\_\_ Major Dents to: \_\_\_\_\_  
 Emergency Equip  None  Has been removed  there are holes in the exterior  There are no holes

Additional Equipment Description: MFG \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A

Lights/ACC removed:  Yes  No N/A

Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No

Mechanic's name: MATT H. Date: 4/13/20

Approved by: [Signature] Date: 4/13/20

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 70505 Vin #: 1FTWF31P65E872307 Fair Market Value: \$ 6000.00

Short Description:  
 Year: 2005 Make: Ford Model: F350-4X Mileage: 92004

This Vehicle:  Starts  Starts with a boost and  Runs  Does not Run  For Parts Only  
 Engine: 6.0 L V 8  Gas  Diesel Engine

This Vehicle was maintained every 5000  Days  Hours  Miles  
 Condition:  Runs  Needs Repair  Is in unknown condition

Repairs Needed (Be specific): \_\_\_\_\_  
 Est Cost of Repairs: \$ \_\_\_\_\_

Date removed from service: \_\_\_/\_\_\_/\_\_\_ Maintenance Records:  Avail  Not Avail

Transmission:  
 Automatic  Manual Condition is  Operable  Needs Repair  Is Unknown  
 Transmission repairs needed: \_\_\_\_\_

Minor Damage to: \_\_\_\_\_ Major Damage to: \_\_\_\_\_  
 AC  No AC AC Condition:  Cold  Unknown Air Bags:  Driver's Side  Dual  
 Cruise  Tilt Wheel  Remote Mirrors  Climate Ctr - PWR:  Windows  Locks  Steering  Seats

Exterior: Color White Windows:  No cracked glass Cracked: \_\_\_\_\_  
 Minor  Dents  Scratches  Dings Tire Condition: Good  Low  Flat  Hubcaps  1  2  3  4

Minor Dents to: \_\_\_\_\_ Major Dents to: \_\_\_\_\_  
 Emergency Equip  None  Has been removed  there are holes in the exterior  There are no holes

Additional Equipment Description: MFG \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

Lic Plates removed:  Yes  No ZONAR Removed  Yes  No  N/A

Lights/ACC removed:  Yes  No N/A

Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No

Mechanic's name: MATT H. Date: 8 10 5 19

Approved by: Steve Cassell Date: 8 15 1 19

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



|   |              |                                   |
|---|--------------|-----------------------------------|
| Inventory CID: <u>71255</u>   | Vin #: _____ | Fair Market Value: \$ <u>1700</u> |
| Short Description:  |              |                                   |
| Year: <u>2007</u> Make: <u>Ford</u> Model: <u>F-150-4X</u> Mileage: <u>81,812</u>   |              |                                   |
| This Vehicle: <input checked="" type="checkbox"/> Starts <input type="checkbox"/> Starts with a boost and <input checked="" type="checkbox"/> Runs <input type="checkbox"/> Does not Run <input type="checkbox"/> For Parts Only  |              |                                   |
| Engine: <u>4.6 L V8</u> <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Diesel Engine  |              |                                   |
| This Vehicle was maintained every <u>5000</u> <input type="checkbox"/> Days <input type="checkbox"/> Hours <input checked="" type="checkbox"/> Miles  |              |                                   |
| Condition: <input checked="" type="checkbox"/> Runs <input checked="" type="checkbox"/> Needs Repair <input type="checkbox"/> Is in unknown condition   |              |                                   |
| Repairs Needed (Be specific): <u>miss fire</u>  |              |                                   |
| Est Cost of Repairs: \$ _____   |              |                                   |
| Date removed from service: ___ / ___ / _____ Maintenance Records: <input type="checkbox"/> Avail <input type="checkbox"/> Not Avail   |              |                                   |
| Transmission:   |              |                                   |
| <input checked="" type="checkbox"/> Automatic <input type="checkbox"/> Manual Condition is <input checked="" type="checkbox"/> Operable <input type="checkbox"/> Needs Repair <input type="checkbox"/> Is Unknown   |              |                                   |
| Transmission repairs needed: _____  |              |                                   |
| Minor Damage to: <u>Front left fender</u> Major Damage to: _____  |              |                                   |
| <input checked="" type="checkbox"/> AC <input type="checkbox"/> No AC AC Condition: <input checked="" type="checkbox"/> Good <input type="checkbox"/> Unknown Air Bags: <input type="checkbox"/> Driver's Side <input checked="" type="checkbox"/> Dual   |              |                                   |
| <input checked="" type="checkbox"/> Cruise <input checked="" type="checkbox"/> Tilt Wheel <input checked="" type="checkbox"/> Remote Mirrors <input type="checkbox"/> Climate Ctr - PWR <input checked="" type="checkbox"/> Windows <input checked="" type="checkbox"/> Locks <input checked="" type="checkbox"/> Steering <input type="checkbox"/> Seats                       |              |                                   |
| Exterior: Color <u>white</u> Windows: <input checked="" type="checkbox"/> No cracked glass Cracked: _____   |              |                                   |
| Minor <input checked="" type="checkbox"/> Dents <input checked="" type="checkbox"/> Scratches <input checked="" type="checkbox"/> Dings Tire Condition: Good <input checked="" type="checkbox"/> Low <input type="checkbox"/> Flat <input type="checkbox"/> Hubcaps <input type="checkbox"/> 1 <input type="checkbox"/> 2 <input type="checkbox"/> 3 <input type="checkbox"/> 4 |              |                                   |
| Minor Dents to: _____ Major Dents to: _____   |              |                                   |
| Emergency Equip <input type="checkbox"/> None <input checked="" type="checkbox"/> Has been removed <input type="checkbox"/> there are holes in the exterior <input type="checkbox"/> There are no holes   |              |                                   |
| Additional Equipment Description: MFG _____ Model _____ Serial # _____  |              |                                   |

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A

Lights/ACC removed:  Yes  No N/A

Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No

Mechanic's name: Gary stretch Date: 6/22/19

Approved by: [Signature] Date: 6/22/19

Additional Comments:



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT  
 FLEET MANAGEMENT DIVISION  
 MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 7D54 Vin #: 1FTRF14W57K90647 Fair Market Value: \$ 2500.00

Short Description:  
 Year: 2007 Make: Ford Model: F150 4x4 Mileage: 126705

This Vehicle:  Starts  Starts with a boost and  Runs  Does not Run  For Parts Only  
 Engine: 4.6 L V 8  Gas  Diesel Engine  
 This Vehicle was maintained every 5000  Days  Hours  Miles  
 Condition:  Runs  Needs Repair  Is in unknown condition  
 Repairs Needed (Be specific): \_\_\_\_\_

Est Cost of Repairs: \$ \_\_\_\_\_

Date removed from service: \_\_\_/\_\_\_/\_\_\_ Maintenance Records:  Avail  Not Avail

Transmission:  
 Automatic  Manual Condition is  Operable  Needs Repair  Is Unknown  
 Transmission repairs needed: \_\_\_\_\_

Minor Damage to: Drivers seat torn Major Damage to: \_\_\_\_\_  
 AC  No AC AC Condition:  Cold  Unknown Air Bags:  Driver's Side  Dual  
 Cruise  Tilt Wheel  Remote Mirrors  Climate Ctr - PWR  Windows  Locks  Steering  Seats

Exterior: Color White Windows:  No cracked glass Cracked: \_\_\_\_\_  
 Minor  Dents  Scratches  Dings Tire Condition:  Low  Flat Hubcaps  1  2  3  4  
 Minor Dents to: \_\_\_\_\_ Major Dents to: \_\_\_\_\_

Emergency Equip:  None  Has been removed  there are holes in the exterior  There are no holes

Additional Equipment Description: MFG \_\_\_\_\_ Model \_\_\_\_\_ Serial # \_\_\_\_\_

Lic Plates removed:  Yes  No ZONAR Removed:  Yes  No  N/A

Lights/ACC removed:  Yes  No N/A

Fuel Card Turned in:  Yes  No Keys/KeyTrak  Yes  No

Mechanic's name: MATT H. Date: 4/17/20

Approved by: [Signature] Date: 4/17/20

Additional Comments: