

CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT FLEET MANAGEMENT DIVISION MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 7/78/ Vin #: [FAHP21870 G 150749] Fair Market Value: \$ 4900'00
Short Description:
Year: 2013 Make: Ford Model: Interceptor Mileage: 63,767
This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
Engine: 3.5 L V Gas Diesel Engine
This Vehicle was maintained every 5,000 Days Hours Hours
Condition: Runs Needs Repair Is in unknown condition
Repairs Needed (Be specific):
Est Cost of Repairs: \$
Date removed from service: _5 / 2 / 2019 Maintenance Records Avail Not Avail
Trapsmission:
Automatic Manual Condition is Operable Needs Repair Is Unknown
Transmission repairs needed:
Minor Damage to: Major Damage to:
✓AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
Cruise Tilt Wheel Remote Mirrors Climate Ctr - PWR Windows Cocks Steering Seats
Exterior: Color Blackfull: Windows: No cracked glass Cracked:
Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 1 2 3 4
Minor Dents to: Major Dents to:
Emergency Equip None Has been removed there are holes in the exterior there are no holes
Additional Equipment Description: MFG Model Serial #
Lic Plates removed: Ves No ZONAR Removed Yes No V/A
Lights/ACC removed: Ves No N/A
Fuel Card Turned in: 🗹 Yes 🗌 No Keys/KeyTrak 🗹 Yes 🗌 No
Mechanic's name: Brad orlando Date: 5 / 2 / 2019
Approved by: Steve Cassell Date: 5/2/19



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT FLEET MANAGEMENT DIVISION MECHANIC'S VEHICLE INSPECTION FORM



7177	. /	10100100
Inventory CID: 7/780 Vin #: IFAHP2L850GISo Short Description:	Fair Market Value: \$	1900.00
Short Description:	3	
Year: 2013 Make: Ford Model: Intarceptor	Mileage: 76, 782	
This Vehicle: Starts Starts with a boost and Runs []	Does not Run 🔲 For Parts	Only
Engine: 3.5 L V 6 Gas Diesel Engine		
This Vehicle was maintained every Days Ho	urs Miles	
Condition: Rans Needs Repair Is in unknown condition		
Repairs Needed (Be specific):		
	Est Cost of Repairs: \$	
Date removed from service: _5 / 2 /2019 Maintenan	ce Records 🗖 Ávail 🔲 Not Av	ail
Transmission:		
☑ Automatic ☐ Manual Condition is ☑ Operable ☐ Needs	Repair□ Is Unknown	٠
Transmission repairs needed:		
Minor Damage to: Major Damage	e to:	·
■AC No AC AC Condition: Cold Unknown Air Bags	Driver's Side Dual	
UCruise ☐ Tilt Wheel ☐ Kemote Mirrors ☐ Climate Ctr - PWR ☐ Wi	ndows Locks Steering] Seats
Exterior: Color Blackfullin Windows: W No cracked glass Cra	cked:	
Minor Dents Scratches Dings Tire Condition: Low □Fla	t Hubcaps 🛛 🛣 🏖 🗜]
Minor Dents to: Major Dents to:		
Emergency Equip ☐ None ☐ Has been removed ☐ there are holes in	n the exterior There are no	o holes
Additional Equipment Description: MFG Model	Serial #	
Lic Plates removed: ☑Yes ☐No ZONAR Removed ☐Yes ☐ No ☑N	I/A	
Lights/ACC removed: Yes No N/A		
Fuel Card Turned in: Yes No Keys/KeyTrak Yes N	О	
Mechanic's name: Brod Ortando Date: 5/2/2	0/9	
Approved by: Steux Cossell Date: 5/2/19		



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT FLEET MANAGEMENT DIVISION MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 7/93/ Vin #: 1FA HP2L 82 E612 2298 Fair Market Value: \$ 4900:00
Short Description:
Year: Make: Ford Model: Intacceptor Mileage: 61.293
This Vehicle: Starts with a boost and Runs Does not Run For Parts Only
Engine: 3.5 L V L Gas Diesel Engine
This Vehicle was maintained every Days HoursMiles
Condition: Rans Needs Repair Is in unknown condition
Repairs Needed (Be specific):
Est Cost of Repairs: \$
Date removed from service: 5 / 2 / 20/5 Maintenance Records Avail Not Avail
Transmission:
Automatic Manual Condition is Operable Needs Repair Is Unknown
Transmission repairs needed:
Minor Damage to: Major Damage to:
☑AC ☐No AC AC Condition: ☐Cold ☐Unknown Air Bags ☐ Driver's Side ☐ Dual
UCruise Tilt Wheel Kemote Mirrors Climate Ctr - PWR Windows Cocks Steering Seats
Exterior: Color Blackfull Windows: No cracked glass Cracked:
Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 1 2 1 1
Minor Dents to: Major Dents to:
Emergency Equip \square None \square Has been removed \square there are holes in the exterior \square There are no holes
Additional Equipment Description: MFG Model Serial #
Lic Plates removed: Yes No ZONAR Removed Yes No N/A
Lights/ACC removed: Yes No N/A
Fuel Card Turned in: Yes No Keys/KeyTrak Yes No
Mechanic's name: Brad ortando Date: 5 / 2 / 20/9
Approved by: Steve Cassell Date: 5/2/19



CITY OF NORTH PORT PUBLIC WORKS DEPARTMENT FLEET MANAGEMENT DIVISION MECHANIC'S VEHICLE INSPECTION FORM



Inventory CID: 71782 Vin #: IFAHP2L83D6 150250 Fair Market Value: \$ 490000
Short Description:
Year: 2013 Make: Ford Model: Intarceptor Mileage: 68,914
This Vehicle: Starts Starts with a boost and Runs Does not Run For Parts Only
Engine: 3.5 L V 6 Gas Diesel Engine
This Vehicle was maintained every Days HoursMiles
Condition: Runs Needs Repair Is in unknown condition
Repairs Needed (Be specific):
Est Cost of Repairs: \$
Date removed from service:/ Maintenance Records Avail Not Avail
Transmission:
☐ Automatic ☐ Manual Condition is ☐ Operable ☐ Needs Repair ☐ Is Unknown
Transmission repairs needed:
Minor Damage to: Major Damage to:
AC No AC AC Condition: Cold Unknown Air Bags: Driver's Side Dual
Cruise Tilt Wheel Kemote Mirrors Climate Ctr - PWR Windows Cocks Steering Seats
Exterior: Color Blackfullen Windows: No cracked glass Cracked:
Minor Dents Scratches Dings Tire Condition: Low Flat Hubcaps 1 2 3 4
Minor Dents to: Major Dents to: Hole in Lift Front Fender m
Emergency Equip None Has been removed there are holes in the exterior here are no holes Small
Additional Equipment Description: MFG Model Serial #
Lic Plates removed: Ves No ZONAR Removed Yes No N/A
Lights/ACC removed: Yes No N/A
Fuel Card Turned in: Ves No Keys/KeyTrak Ves No
Mechanic's name: Brad Ortando Date: 5 / 2 / 2019
Approved by: Steve Cassell Date: 5 / 2 / 19